



Rubber Back-up Ring

Size indication & tolerance chart



Rubber back-up ring (80 Shore A) is usually used with O-ring in order to bear greater pressure. Customer can order according to the size of o-ring for convenience.



ID	Tol (+/-)	C/S	Tol (+/-)
0 - 1.79	0.10	0 - 1.79	0.07
1.80 - 6.29	0.13	1.80 - 2.64	0.08
6.30 - 10.59	0.14	2.65 - 3.54	0.09
10.60 - 18.99	0.17	3.55 - 5.29	0.10
19.00 - 31.49	0.22	5.30 - 6.99	0.13
31.50 - 41.19	0.30	7.00 - 8.00	0.15
41.20 - 51.49	0.36	8.01 - 10.00	0.20
51.50 - 64.99	0.44	10.01 - 15.00	0.25
65.00 - 82.49	0.53	15.01 - 25.00	0.35
82.50 - 121.99	0.65	25.01 - 100.00	0.45
122.00 - 184.99	0.90		
185.00 - 257.99	1.20		
258.00 - 324.99	1.60		
325.00 - 411.99	2.10		
412.00 - 514.99	2.60		
515.00 - 649.99	3.20		
650.00 - 670.00	4.00		
670.01 - 999.00	5.00		
999.01 - 1200.00	6.00		
1200.01 - 1500.00	7.00		
1500.01 - 1800.00	8.00		
1800.01 - 2000.00	9.00		